# **Melges 24 Class Rule Change Proposal**

Name and Surname	International Melges 24 Class Association	
	,	
Position in Nominating Body	Technical Committee	
Email		
Title of the motion, amendment, nomination	F.3.2(d) CONSTRUCTION	

#### **Topics concerned**

	Constitution	E	Events
х	Class Rules		Technical Issues
	Regatta Regulations	(	General Policies
	Nomination		

#### **Current Rule:**

None

## Proposed New Rule:

*F.3.2(d).* External re-enforcement used as per the licensed builder's specification, shall not be measured as part of the spar's cross-sectional dimensions.

### Reason:

With a spiral wound mast, the re-enforcing is located on the outside of the spar section as opposed to inside on the moulded spars. This additional thickness may exceed the maximum allowable cross-sectional dimensions. The class rules need to allow the licensed builders to be able to re-enforce the spar build using either construction technique.