Melges 24 Class Rule Change Proposal

Name and Surname	International Melges 24 Class Association	
Position in Nominating Body	Technical Committee	
Email		
Title of the motion, amendment, nomination	H2 Fittings – Cabin Main Halyard	

Topics concerned

	Constitution	Events
х	Class Rules	Technical Issues
	Regatta Regulations	General Policies
	Nomination	

Current Rule:

H2. Fittings – Cabin "Cleat and cheek block on starboard side for main halyard" – Extra cleats or stopper may be added. An additional maximum 4:1 with cleat purchase may be added to assist with halyard tension.

Proposed New Rule:

H2. Fittings – Cabin "Main halyard starboard side with cheek block" – Optional cleat or stopper may be added. An additional maximum 4:1 purchase with cleat may be added to assist with halyard tension.

Reason:

Housekeeping – The additional 4:1 purchase with cleat makes the original cleat mounted on the side of the compression post redundant. Many boats do not have the original side mounted cleat. This change aligns the class rules with the current state of the fleet.